## **Trade Waste Inspection Report**

	1	е пізрессіон кероге	
Business Name	Cooinda Residential Aged Care		
Address	12-14 Neate Street	Assessment No.	01368-10000000
Date of Inspection	20/05/2014		
Trade Waste Activity	Day Care Centre – hot food		
Classification	А	Charging category	2
Operation Details	Nursing Home – 25 residents (80 meals/day); wash up sink 2/day, prep sink 1/day, dishwasher 30/day; steam oven from 6.30am-1pm		
	Meryula – 16 residents; dishwasher sinks 6/day, dishwasher 6/day; washer 2/day; pan sanitisers rarely used		
	<u>Lodge</u> – 12 residents; w	ash up sinks 5/day, dishwa	sher 3/day
	Hostel – 37 residents; r 1/week (12 washes)	inse sink 5 mins/day, dishw	asher 30/day; hair salon
	"	2/day) and macerator (3/d 'day (Fridays). All mop buck Cooinda	
	<u>Villas</u> – 14 two-bedroor	n units	
Pretreatment	Sink screens, lint filters, grease arrestor (undersized)		
Requirements for Compliance	Sink screens (all food prep areas), upgrade grease arrestor (1000 L) and connect/install grease arrestor to kitchens, cooling pit (laundries), disconnection of pan macerators		
Estimated Volume Trade Waste	4.65 kL/d (0.68 kL/d from food prep)	TWDF (Estimated) 25 %	TWDF (Guidelines) Not given
Comments/Photos			
Laundry: pan macerator, sanitiser and dishwasher (for pans) Washers (right)	On NOT FE AND 5 PATE THAN 5 PATE THAN 5		
Hostel: dishwasher and sinks (left)			
Hairdresser: wash basin with sink screen			
			Continued over next page

Continued	Cooinda Residential Aged Care		
Meryula: wash up sink and dishwasher (left) Pan sanitisers (right)			
Nursing Home: wash up sink (left), dishwasher (middle), prep sink (right)	PLASE PROFITE HIS HIS PROFITE HIS PROF		
Nursing Home: steam oven			
Lodge: Electrolux dishwasher (left) and washer (for residents' personal items)			
Grease arrestor (approx. 200 L) connected to Meryula			